


Release Notes

Cobalt Cube®



Contents

1	Cobalt Cube Android Image	2
1.1	New functionality	2
1.2	Bug fixes	2
1.3	Known issues	2
2	Cobalt Cube Home	2
2.1	New functionality	2
2.2	Bug fixes	2
2.3	Known issues	2
3	MDT Control	3
3.1	New functionality	3
3.2	Bug fixes	3
3.3	Known issues	3
4	MCS Control	3
4.1	New functionality	3
4.2	Bug fixes	3
4.3	Known issues	3
5	Smartphone Control	3
5.1	New functionality	3
5.2	Bug fixes	3
5.3	Known issues	4
6	Genisys Control	4
6.1	New functionality	4
6.2	Bug fixes	4
6.3	Known issues	4
7	Cobalt Link+ Server for Windows	4
7.1	Supported Windows OS Versions	5
7.2	New functionality	5
7.3	Bug fixes	5
7.4	Known issues	5
8	Pathfinder Control	5
8.1	New functionality	5
8.2	Bug fixes	5
8.3	Known issues	5
9	Camera Feeds	5
9.1	New functionality	5
9.2	Bug fixes	5
9.3	Known issues	6
10	Cobalt Update	6
10.1	New functionality	6
10.2	Bug fixes	6
10.3	Known issues	6
11	My Settings	6
11.1	New functionality	6
11.2	Bug fixes	6
11.3	Known issues	6
12	Bluetooth Media Player	6
12.1	New functionality	6
12.2	Bug fixes	6
12.3	Known issues	6

1 Cobalt Cube Android Image

1.1 New functionality

N/A

1.2 Bug fixes

N/A

1.3 Known issues

Issue Number	Description
MOB-24413	Cobalt Cube HDMI output will not function if an HDMI cable with Ethernet and a HDMI Ethernet enabled monitor are used.
MOB-22417	Audio focus doesn't always stay on the Link+ Server device while "bridging" via Android Auto.
MOB-24449	System UI can crash when a Bluetooth headset is attached to the Cobalt Cube.
MOB-27521	When multiple Bluetooth A2DP audio sources are connected to the Cobalt Cube, the correct source may need to be manually selected through Android settings before it can be used.
MOB-27596	Moving the navigation bar sometimes results in the buttons not being rendered properly. Rebooting the Cobalt Cube should fix this issue.
MOB-31142	Some vehicle screens can cause the Cobalt Cube to get stuck in portrait mode on the initial setup. A reboot clears this.
MOB-31607	Sometimes attempting to apply two different activation codes one after another will fail. A reboot in between resolves the issue.
MOB-32112	Sometimes Bluetooth A2DP indicator does not reflect the accurate connected state of a device.

2 Cobalt Cube Home

2.1 New functionality

N/A

2.2 Bug fixes

N/A

2.3 Known issues

Issue Number	Description
MOB-27151	The right arrow icon sometimes appears in the middle of the home screen after the number of home apps has been changed.
MOB-27543	Invalid (shorter than 8 characters) hotspot passwords can be set in Cobalt Cube Hidden Settings, resulting in the hotspot not starting.
MOB-30217	When the 'Start on boot' toggle is disabled in the DHCP Server Configuration, the configuration is reset.
MOB-31851	The activation upgrade dialog can show codes that may not be applicable to the particular Cobalt Cube.

3 MDT Control

3.1 New functionality

N/A

3.2 Bug fixes

N/A

3.3 Known issues

Issue Number	Description
MOB-23414	"Menu" icons might only be partially rendered if moved too quickly.
MOB-27338	Some vehicle screens may not release a touch after 4 or more touch points were used.
MOB-32414	When using three or more monitors, the Windows server may sometimes not capture the expected screen.
MOB-32400	Popup message informing a user of a configuration problem sometimes does not show.
MOB-32460	Windows server tray app option to show tray logs may produce an error on Windows 11.

4 MCS Control

4.1 New functionality

N/A

4.2 Bug fixes

N/A

4.3 Known issues

N/A

5 Smartphone Control

5.1 New functionality

N/A

5.2 Bug fixes

N/A

5.3 Known issues

Issue Number	Description
MOB-23804	Application does not adapt its scaling correctly after being forced into split screen mode.
MOB-27543	It is possible to enter a hotspot password that is too short (less than eight characters).
MOB-29028	On iOS, if a connection is established while the Cobalt Link+ app is not in the foreground, touch controls will not work until the app is opened.
MOB-30095	The Cobalt Cube must be fully booted before connecting a supported device to Smartphone Control via USB.
MOB-30170	On iOS, if the Cobalt Cube Bluetooth pairing is forgotten, Smartphone Control will not try to re-pair to the iPhone, leading to a view only session.
MOB-31461	Unpair dialog is shown even if the selected device was never paired to the Cobalt Cube (e.g. was using USB touch input).
MOB-31563	Sometimes when an Android device previously connected via wireless is plugged in via USB Smartphone Control will not allow a connection until that device is unplugged again.
MOB-31588	Some Android 16 devices are occasionally not able to pair with the Cobalt Cube when using manual pairing resulting in a view only session. Android devices will first try the new device side pairing to mitigate this issue.
MOB-31817	In rare cases the mirrored screen will be black after starting a connection. Exiting and re-opening Smartphone Control will resolve this.
MOB-31735	Occasionally a lower resolution than optimal can be selected.
MOB-31585	On some OnePlus phones, having screen orientation lock enabled can stop the Bluetooth pairing dialog from showing on the phone side. As a workaround, disabling screen orientation lock fixes the issue.

6 Genisys Control

6.1 New functionality

N/A

6.2 Bug fixes

N/A

6.3 Known issues

N/A

7 Cobalt Link+ Server for Windows

7.1 Supported Windows OS Versions

Operating SystemSupported	Description
Windows 11	Yes
Windows 10	Yes
Windows 8.1	Not currently supported. Please contact your VNC Automotive technical representative if you require support for this operating system.
Windows 8	Not currently supported. Please contact your VNC Automotive technical representative if you require support for this operating system.
Windows 7	Not currently supported. Please contact your VNC Automotive technical representative if you require support for this operating system.

7.2 New functionality

N/A

7.3 Bug fixes

N/A

7.4 Known issues

Issue Number	Description
MOB-27064	Cobalt Link+ Server will stop screen capture and event injection if the “switch user” feature in Windows is used.
MOB-31974	The Windows Server is not generating tray logs.

8 Pathfinder Control

8.1 New functionality

N/A

8.2 Bug fixes

N/A

8.3 Known issues

N/A

9 Camera Feeds

9.1 New functionality

N/A

9.2 Bug fixes

N/A

9.3 Known issues

Issue Number	Description
MOB-29512	Thumbnail images can be over-exposed or blank.
MOB-29532	In rare situations the app can become unresponsive - we recommend rebooting the Cobalt Cube to resolve this issue.

10 Cobalt Update

10.1 New functionality

Feature	Description
TOP-5515	Upgraded OTA System Update Service infrastructure for improved security and reliability.

10.2 Bug fixes

N/A

10.3 Known issues

Issue Number	Description
MOB-31170	OTA System Update Service won't connect if the system date on the Cobalt Cube is not correct.

11 My Settings

11.1 New functionality

N/A

11.2 Bug fixes

N/A

11.3 Known issues

N/A

12 Bluetooth Media Player

12.1 New functionality

N/A

12.2 Bug fixes

N/A

12.3 Known issues

N/A

Let's discuss your project

As industry pioneers, we will help you cut through the complexity and deliver ingenious connectivity technology for the vehicles of tomorrow.

Get in contact via:

www.vncautomotive.com

technicalsupport@vncautomotive.com

No part of this documentation may be reproduced in any form or by any means or be used to make any derivative work (including translation, transformation or adaptation) without explicit written consent of VNC Automotive.

All information contained in this document is provided in commercial confidence for the sole purpose of use by an authorized user in conjunction with VNC Automotive products. The pages of this document shall not be copied, published, or disclosed wholly or in part to any party without VNC Automotive prior permission in writing, and shall be held in safe custody. These obligations shall not apply to information which is published or becomes known legitimately from some source other than VNC Automotive.

